


Mount Zion - Female Union Band Society Cemeteries - Funding Need for Restoration of Staircase Handrails and Stairs Leading to the Historic Cemetery Vault



Restoration of the Handrails and Staircases leading to the historic Cemetery Vault is needed to provide visitors with a much safer support system than is offered by existing rope and posts, and decayed stairsteps.


The safety and esthetic elements of the new railings (specifications below) are based on designs employed by the National Park Service for pathways located in NPS managed parklands.

The total investment required is \$31,238. Please consider an individual or organization financial gift enabling us to complete this important project before yearend. Your donation can address key elements of the restoration:

- Curved staircase extension, new stairs bedding and treads, and landing grooming - \$10,787
- Curved staircase railings crafted in accordance with National Park Service design guidelines - \$7,245
- Direct descent/ascent (high incline) staircase stairs bedding and treads, and landing grooming - \$9,324
- Direct descent/ascent staircase railings crafted to National Park Service design guidelines – \$3,882

[Please consider an individual or organization gift to enable us to complete this important project this year.](#)

National Park Service design and construction specifications for railing systems for pathways located in NPS managed parklands



 DONATE